



February 13, 2006

Ms. Robbie Rogers  
Sumter County Planning and Zoning  
209 N. Florida Street  
Bushnell, Florida 33513

RE: Florida Crushed Stone-Center Hill Mine  
Permit #MI 91-6 - Monthly Water Monitoring Data

Dear Ms. Rogers:

Please find the attached revisions for the above referenced permit.

Due to clerical errors the following were recorded incorrectly.  
Dist. I.D. no. 1, dist. I.D. no. 22, and Dist. I.D. no. 11.

The following are the revised elevations.

Dist. I.D. 1 is 86.5  
Dist. I.D. 22 is 86.5  
Dist. I.D. 11 is 86.3

If you have any questions, please contact me at (352) 796-3522.

Sincerely,

J. Scott Hickman

  
Field Supervisor



**Center Hill Mine - Monthly Water Levels**  
**WUP No. 200213.04**

### Monitor Wells: Monthly Frequency

[illegible]

Well	MW-19	MW-20	MW-21	MW-67	MW-68	MW-61	MW-60	MW-68
Location	E. PL	E. PL	E. PL	S.E. Cor	S. PL	S.W. Cor.	W. PL	W. PL
District ID #								
Condition No								
MP Elev (ft MSL)	98.06	98.40	90.37	91.28	90.87	89.60	90.83	98.09
1/15/2006								
1/30/2006	94.25	94.00	83.37	86.39	86.77	85.89	84.33	79.49
2/15/2006								
2/29/2006								
3/15/2006								
3/30/2006								
4/15/2006								
4/30/2006								
5/15/2006								
5/30/2006								
6/15/2006								
6/30/2006								
7/15/2006								
7/30/2006								
8/15/2006								
8/30/2006								
9/15/2006								
9/30/2006								
10/15/2006								
10/30/2006								
11/15/2006								
11/30/2006								
12/15/2006								
12/30/2006								